

## **MEDIA RELEASE**

Toyota Motor Corporation has announced a Special Service Campaign for selected VIN numbers impacting 2016 to 2018 Toyota CH-R and 2015-2018 Toyota Prius.

There is a chance of malfunction as there is an engine wire harness which is connected to the hybrid vehicle Power Control Unit. A portion of the wire harness could contact the cover and excessive vibration could cause the insulation on the wires to wear over time and expose the core wire.

From information received from Toyota Motor Corporation, within Fiji there are only Ten (10) units impacted and of which two (2) were purchased outside of the ASCO Motors internal fleet. ASCO Motors has successfully contacted all customers and arranged for an inspection of the units in line with the special service campaign requirements.

For further information, please contact the Company Secretary – Mr. Ronald Kumar on email, rkumar@asco.com.fj.

Craig Sims

Chief Executive Officer

12-09-2018

Ronald Kumar

Company Secretary

12-09-2018